

Motor Vehicle Incident Report

Contemporaneous record prepared at the scene by the reporting driver

Dana Ortiz
Police report PPD-2026-04417
Prepared 9/14/2026, 6:21:00 PM

AT A GLANCE			
Date & time of crash	9/14/2026, 5:42 PM	Vehicles involved	2
Location	1412 N Lake Powell Blvd, Page, AZ 86040	Injuries reported at scene	2 — see §6
Police attended	Yes	Photographs	19 exhibits
Other driver	Randall T. Hobbs	Their insurer	Sagebrush Mutual Insurance

1 THE INCIDENT

Date / time of crash	9/14/2026, 5:42 PM
Recorded in app at	9/14/2026, 5:49:11 PM
Street address	1412 N Lake Powell Blvd, Page, AZ 86040
Cross street / mile marker	At S Navajo Dr — second light past the Safeway
Direction of travel	Southbound
Coordinates	36.91456, -111.45589
Road & light conditions	Sun glare, Light / stop sign involved
Vehicles clear of the roadway	Yes — photographed from off the roadway

2 DRIVERS & INSURANCE

REPORTING DRIVER		OTHER DRIVER	
Name	Dana Ortiz	Name	Randall T. Hobbs
Phone	(928) 555-0164	Phone	(928) 555-0173
Address	407 W Aero Ave, Page, AZ 86040	Address	88 Elm Dr, Page, AZ 86040
Driver's license #	D02218844	Driver's license #	D04471290 (read from licence barcode)
Vehicle	2021 Toyota RAV4 XLE	Date of birth	04/18/1979
Plate	AZ · RAV8812	Vehicle	2019 Chevrolet Silverado 1500
VIN	2T3P1RFV6MC155903	Plate	AZ · TRK4482
Insurer	Desert Star Insurance	VIN	3GCUKREC9KG204417 (read from registration)
Policy #	DS-4410927	Insurer	Sagebrush Mutual Insurance (read from card)
		Policy #	SM-77341902
		Policy period	03/01/2026 – 03/01/2027
		Registered owner	Hobbs Excavating LLC

3 POLICE

Officer attended the scene	Yes
Agency	Page Police Department
Officer / badge	Ofc. J. Nakai, badge 214
Report #	PPD-2026-04417

4 WITNESSES

Witness 1	Carmen Oyala · (928) 555-0118
Witness 2	Glen Petersen · (435) 555-0142

5 VEHICLE REMOVAL & STORAGE

Tow company	Big Lake Towing
Vehicle taken to	Big Lake yard, 2100 Coppermine Rd, Page AZ — \$65/day storage

6 INJURIES REPORTED

When	Reported at	Reported
At the scene	9/14/2026, 5:42 PM	Neck pain, Headache
24-hour check-in	9/15/2026, 6:02:00 PM	Neck pain, Back pain, Headache
72-hour check-in	9/17/2026, 6:05:00 PM	Back pain

Reported by the driver at the times shown. This is a record of what was felt and when — it is not a medical opinion or diagnosis.

7 DRIVER'S ACCOUNT

I was stopped at the light behind two other cars. I heard tyres and then was hit from behind hard enough to push me into the crosswalk. The sun was low and straight down the road. The other driver said he was looking at his phone mount. We both pulled into the bank lot before taking any photographs.

A voice recording made by the driver at the scene accompanies this report as a separate audio file.

8 PHOTOGRAPHIC EXHIBITS (19)

Exhibit 1	Accident view — the whole scene	Wide — from the front	9/14/2026, 5:45:42 PM
Exhibit 2	Accident view — the whole scene	Wide — from behind	9/14/2026, 5:46:56 PM
Exhibit 3	Accident view — the whole scene	Left side	9/14/2026, 5:48:10 PM
Exhibit 4	Accident view — the whole scene	Right side	9/14/2026, 5:49:24 PM
Exhibit 5	Accident view — the whole scene	Skid marks & debris	9/14/2026, 5:50:38 PM
Exhibit 6	Accident view — the whole scene	Signs & signals	9/14/2026, 5:51:52 PM
Exhibit 7	My car	Your car — front-left	9/14/2026, 5:53:06 PM
Exhibit 8	My car	Your car — front-right	9/14/2026, 5:54:20 PM
Exhibit 9	My car	Your car — rear-left	9/14/2026, 5:55:34 PM
Exhibit 10	My car	Your car — rear-right	9/14/2026, 5:56:48 PM
Exhibit 11	My car	Your damage — close-up	9/14/2026, 5:58:02 PM
Exhibit 12	My car	Your odometer	9/14/2026, 5:59:16 PM
Exhibit 13	Their car	Their car — corners	9/14/2026, 6:00:30 PM
Exhibit 14	Their car	Their damage — close-up	9/14/2026, 6:01:44 PM
Exhibit 15	Their car	Their license plate	9/14/2026, 6:02:58 PM
Exhibit 16	Their car	Their VIN	9/14/2026, 6:04:12 PM
Exhibit 17	Their licence, insurance & registration	Their driver's license	9/14/2026, 6:05:26 PM
Exhibit 18	Their licence, insurance & registration	Their insurance card	9/14/2026, 6:06:40 PM
Exhibit 19	Their licence, insurance & registration	Their registration	9/14/2026, 6:07:54 PM

Where the vehicles came to rest, the road, and the signs or signals involved.

EXHIBIT 1

Wide — from the front

[sample photograph]

Wide — from the front

9/14/2026, 5:45:42 PM · 36.91456, -111.45589

EXHIBIT 2

Wide — from behind

[sample photograph]

Wide — from behind

9/14/2026, 5:46:56 PM · 36.91458, -111.45590

EXHIBIT 3

Left side

[sample photograph]

Left side

9/14/2026, 5:48:10 PM · 36.91460, -111.45591

EXHIBIT 4

Right side

[sample photograph]

Right side

9/14/2026, 5:49:24 PM · 36.91462, -111.45592

EXHIBIT 5

Skid marks & debris

[sample photograph]

Skid marks & debris

9/14/2026, 5:50:38 PM · 36.91464, -111.45593

EXHIBIT 6

Signs & signals

[sample photograph]

Signs & signals

9/14/2026, 5:51:52 PM · 36.91466, -111.45594

My car

6 PHOTOGRAPHS

The reporting driver's vehicle: every corner, the damage, and the odometer.

EXHIBIT 7

Your car — front-left

[sample photograph]

Your car — front-left

9/14/2026, 5:53:06 PM · 36.91468, -111.45595

EXHIBIT 8

Your car — front-right

[sample photograph]

Your car — front-right

9/14/2026, 5:54:20 PM · 36.91470, -111.45596

EXHIBIT 9

Your car — rear-left

[sample photograph]

Your car — rear-left

9/14/2026, 5:55:34 PM · 36.91472, -111.45597

EXHIBIT 10

Your car — rear-right

[sample photograph]

Your car — rear-right

9/14/2026, 5:56:48 PM · 36.91474, -111.45598

EXHIBIT 11

Your damage — close-up

[sample photograph]

Your damage — close-up

9/14/2026, 5:58:02 PM · 36.91476, -111.45599

EXHIBIT 12

Your odometer

[sample photograph]

Your odometer

9/14/2026, 5:59:16 PM · 36.91478, -111.45600

The other driver's vehicle: corners, damage, plate and VIN.

EXHIBIT 13

Their car — corners

[sample photograph]

Their car — corners

9/14/2026, 6:00:30 PM · 36.91480, -111.45601

EXHIBIT 14

Their damage — close-up

[sample photograph]

Their damage — close-up

9/14/2026, 6:01:44 PM · 36.91482, -111.45602

EXHIBIT 15

Their license plate

[sample photograph]

Their license plate

9/14/2026, 6:02:58 PM · 36.91484, -111.45603

EXHIBIT 16

Their VIN

[sample photograph]

Their VIN

9/14/2026, 6:04:12 PM · 36.91486, -111.45604

Photographed at the scene with the other driver present.

EXHIBIT 17

Their driver's license

[sample photograph]

Their driver's license

9/14/2026, 6:05:26 PM · 36.91488, -111.45605

EXHIBIT 18

Their insurance card

[sample photograph]

Their insurance card

9/14/2026, 6:06:40 PM · 36.91490, -111.45606

EXHIBIT 19

Their registration

[sample photograph]

Their registration

9/14/2026, 6:07:54 PM · 36.91492, -111.45607

9 HOW THIS RECORD WAS MADE

Captured with	CrashKit, on the reporting driver's own phone
Photographs	Taken through the app's camera at the scene. The app does not import images from the phone's photo library.
Times shown	The phone's clock at the moment each photograph was taken or each entry was made.
Coordinates	From the phone's location service, where it was available and permitted.
Where it has been kept	On the reporting driver's device. CrashKit operates no servers and holds no copy.
Full-resolution originals	Held on the device and available on request.

Signature of reporting driver — Dana Ortiz

Date

Prepared with CrashKit. This document is a factual record assembled by the vehicle's driver from what they observed and photographed. It is not legal advice, not medical advice, and not an adjuster's or investigator's finding. Nothing in it determines fault.